



Nordson MEDICAL
805 West 71st Street
Loveland, CO 80538, USA

+1.888.404.5837
+1.970.267.5200
nordsonmedical.com

Product Change Notification

Date of Correspondence	Planned Date of Change Implementation
8/13/20	Immediate
Change Notification Number	Sub-Supplier Change Notification Number
1160636	N/A

Product(s) Affected

Part Number(s)			
1040-5	50AC-S35162	CF631-CM072	N440-1
1050-2	50AC-S35242-2	CF824-81	N440-2
10ACV-SE2-02	50AC-S9-06LB	CF896-001	N670-9022
1401-1	50ACV-PB2-04BLK	CF898-001	NVF20PC
1402-6005	50ACV-PB9-04	CF977-9	NVF20VPC
1600-6005	50ACV-PF17-04	CF988-6005	NVF25PC
1620-2	50ACV-SB2-04BLK	CF-AD-6005	NVF37PC
16210-2	50ACV-SF17-04	CM050	NVF41PC
16210-6005	50BAC-S2-06	D-1	NVFMILL-001
16210-J1A	50PE-S35240	FCFFM-014	NVfy36PC
16445-1	50PP-P75170	FCFM-018	OP-770 430 GREY
16445-2	50PPV-PE1-06	FCFMR-2A-001	P20AC-PB4-04
1801-6005	60PPV-PV2-08	FCFMR-2A-004	P20AC-S35176
1802-1	60PPV-SE3-04	FMTLT-6005	P20ACV-SB1-02
1810-2	60PPV-SV2-08	FTLC-9	P20ACV-SB2-03
18210-2	60PPX-S3-12	FTLL013-4	P20ACV-SB2-04
18240-J1A	60PSV-SE3-06	FTLL035-5	P20CB-PB9-04
18420-J1A	60PSV-SE3-08	FTLL035-9002	P40AC-PB1-06
18430-6005	65PS-PFB1-08	FTLL250-06	P40AC-PB3-06NN
18FTLL-4	65PS-S2-12	FTLL360-9-AN	P40AC-S1-04BSPT
18LFTLL-4	65PS-S35175	FTLL410-9010	P40AC-S2-06
18LFTLL-5	6PTT210-6005	FTLL445-9	P40AC-S3-04NN
18MTLL-5	6S100108	FTLL450-J1A	P40ACV-PB2-04
18MTLL-J1A	6S100208	FTLLE-2	P40ACV-PB2-06
2040-2	6S150208	FTLLP-CM050	P40ACV-PB3-04NN
20AB-P75136	6S200108	FTLLSB013-1	P40ACV-PB3-06NN
20AB-P75137	6S250108	FTLT-J1A	P40ACV-SB1-04
20AB-P75138	6S250208	G42MPGR-TF075-E	P40ACV-SB1-04BSPT
20AB-P75139	930AS-0001	Grand Total	P40ACV-SB2-04
20AC-P75155	930JS	K410-6005	P40ACV-SF1-04
20AC-P75157	930JS-03	K420-2	P40ACV-SF1-06
20AC-S2-01BLU	930JS-06	KFTL-9	PIP080-J1A
20AC-S3-02BLU	930JS-07	KL210-J1A	PIP240-5
20AC-S3-02NA	930JS-08	KL220-2	PIP40-2
20AC-S3-02NLN	ABR013-6012-2	KL230-J1A	PIP60-2
20AC-S35227	ABR013-J1A-3	L220/210-2	PQCF18-PP-001
20ACV-PB2-02YEL	AC1000103	L220-J1A	PQCLM3230-PP-001
20ACV-PB2-03RED	AD-9	L230/210-9	PQCM3230-AC-001
20ACV-PB3-01BLU	AF7500077	L230-3	PQCVF3230-AC-001
20ACV-PB3-01GRN	AF7500077D	L230-4	PQCVLM3260-PP-001
20ACV-PB4-02BLK	AF7500155	L30-J1A	PQCVM3230-AC-001

20ACV-PE2-01	AF7500285C	L430/220-9002	PV00-1031C
20ACV-PV1-02BLK	AF7500584	L430/410-1	PV00-1031M
20ACV-SB2-01BLU	B-1	L975-9	PV00-3062C
20ACV-SB2-02RED	BDF16-6005	LE32-1	PV00-3062M
20ACV-SB3-01BLK	BDJ01-81	LE7220-9	PV00-5062C
20ACV-SB3-01YEL	BDJ02-81	LE7230-6012	PV00-6062C
20ACV-SB3-02NA	BDJ03-40	LLDPE02-3031C	PV02-1031M
20ACV-SB3-02RED	BDJ05-81	LT232-1	PV02-5062C
20ACV-SB3-04NA	BDJ06-81	LT323-9	RMLLR-J1A
20ACV-SB8-04NL	BDJ11-81	M6430-2	S220-J1A
20ACV-SE3-01NN	BDJ12-81	M6430-J1A	S30-2
20ACX-PE1-02	BDJ13-81	MLB065-9	S450-6005
20ACX-S2-02	BDJ14-81	MLBP-8012	SBLF013-CM030
20CB-PB10-025	BDJ15-81	MLLR-9002	SBLF035-8B
20CB-PB13-04	BDM18-81	MLRL013-2	SBLF035-CM030
20CB-S1-04	BDMD-81	MLRL025-2	SBLM013-002
20CBV-SV1-02	BDML210-81	MLRL035-9002	SCV06018
20NBV-PE8-04	BDML220-40	MLS004-9	SCV06052
20NBV-SE1-02	BDML230-40	MLS025-9	SCV12052
20PP-S1-04MALD	BDML230-9002	MLSLP-6005	SFMN655B-6005
20PP-S3-01	BDML410-81	MQCF230-1	SFTLL-2
20PPV-PE2-01MORG	BDML420-81	MQCF230-5	SFTLL-6012
20PPV-SE9-04MALD	BDML430-40	MQCRM240-001	SILC7002775
20PPV-SS1-02XL	BDMMTL-81	MSL035-9	SP-20
20PPV-SV1-04	BDMR210-40	MSL035-J1A	T080/070-0
20SVK-01	BDMR210-9002	MSL055-1	T100-0
3050-2	BDMR220-40	MTL20-9	T210/220-2
3050-5	BDMR240-81	MTLL035-J1A	T220/230-J1A
30AC-S2-03BLK	BDMR420-81	MTLL210-06	T230/210-9
30ACV-PV10-04	BDMR445-81	MTLL230-06	T230R210-J1A
30ACV-SV3-04PN	BDMRP-40	MTLL230-4	T250-9
40AC-P7554	BDMT220-81	MTLL230-6012	T250-J1A
40AC-PB9-06	BDMT430-81	MTLL240-6012	T410/420-1
40AC-PBN4-04	BDMX-81	MTLL250-2	T410/420-J1A
40AC-PE6	BP KIT-001	MTLL410-J1A	T420/410-J1A
40AC-S17-04	BPCL230-10	MTLL450-3	T420/430-6005
40AC-S18-04	BPMMTLL-1	MTLL450-5	T430/420-6005
40AC-S9-06	BPMMTLL-5	MTLL450-J1A	T690-9
40ACV-101	BPSF156-D1B	MTLLP-06	TBA2025-002
40ACV-PB2-06BLK	BSFTLL-2002	MTLLP-07	TBA2052-001
40ACV-PB3-06	C107-A	MTLLP-4	TBA2062-002
40ACV-PBN3-06	C169	MTLLP-5	TBA4030P-001
40ACV-PBN4-06	C302	MTLLP-6012	TBA4030P-002
40ACV-PE2-04	C303	MTLLP-6017	TECS116-6005
40ACV-PV2-04	C332	MTLR210-6005	U30-2
40ACV-SB3-05NLN	CA066-001	MTLR230-9	VPB0850400N
40ACV-SBN2-06	CA093-001	MTLS220-81	VPM0480201N
40ACV-SBN3-06	CA160-002	MTLS220-J1A	X10-6005
40ACV-SF18-04	CCLR-6005	MTLS230-81	X240-5
40CB-P75109	CF097-6005	MTLS230-9	X240-J1A
40CB-P75113	CF1065-6005	MTLS240-2	X410-1
40CB-PB4-04	CF1069-6005	MTLS240-5	X445-J1A
40CB-PB4-06	CF1074-1	MTLS240-9	XL230-6012



Nordson MEDICAL
 805 West 71st Street
 Loveland, CO 80538, USA

+1.888.404.5837
 +1.970.267.5200
 nordsonmedical.com

40CB-PV9-06	CF189-1	N007/004-J1A	XL410-J1A
40CB-S35119	CF190-1	N007-J1A	XL430-2
40CBV-PBN3-04	CF191-07	N013-2	XL430-J1A
40CBV-SB3-05	CF192-3	N025/007-2	XQCVBM770-1006-B
40CBV-SB8-06	CF213-3	N025/013-2	XT210-6005
40PP-S35221	CF301-J1A	N035/013-2	XT210-J1A
40PPV-SE3-04MALDNA	CF439-6015	N065/035-2	XT230-J1A
42AC-S35226	CF471-6015	N070/013-0	XT410-J1A
5050-J1A	CF482-6005	N090-6005	Y070-0
50AC-PB9-06	CF513-CM030	N430/410-2	Y230-6012
50AC-S35161	CF607-07	N430/420-J1A	Y240-2
50AC-S35162	CF608-5	N430-J1A	Y430-J1A

Change Description

Products listed will no longer be available.

Reason for Change

As the business continues to grow, and to maintain efficiencies to best serve our customers, Nordson MEDICAL will rationalize slow moving products to ensure a relevant product mix. As a result of this rationalization procedure the products listed will no longer be available for sale.

Change Level

Level 1

Level 2

Level 3

Emergency

Implementation Procedure

Products are subject to immediate discontinuation. Please contact your Account Manager for a suggested substitute or alternative.

Single Point of Contact	Email Address
Customer Service	change@nordsonmedical.com