



Nordson MEDICAL
805 West 71st Street
Loveland, CO 80538, USA

+1.888.404.5837
+1.970.267.5200
nordsonmedical.com

Product Change Notification

Date of Correspondence	Planned Date of Change Implementation
11/14/2019	Within 90 days of Correspondence
Change Notification Number	Sub-Supplier Change Notification Number
1063227 REV A	N/A

Product(s) Affected

Part Number(s)			
DCV114-001, DCV115-001, DCV118-001, DCV125-001, DCV127-001			
Change Description			
The assembly weld joint design will be modified to be a shear weld geometry. This will affect the interior geometry only. The external geometry will remain the same.			
Reason for Change			
The assembly weld joint is being changed to a shear weld geometry to eliminate weld flash that is entering into the flow path during the weld process.			
Change Level			
Level 1 <input checked="" type="checkbox"/>	Level 2 <input type="checkbox"/>	Level 3 <input type="checkbox"/>	Emergency <input type="checkbox"/>

Implementation Procedure

The changes described will be implemented as a rolling change. The designs and drawings will increment revision to indicate changes made to the internal weld geometry.

Single Point of Contact	Email Address
Customer Service	sales@nordsonmedical.com