

Product Change Notification

Date of Correspondence	Planned Date of Change Implementation
3/10/2020	Immediate
Change Notification Number	Sub-Supplier Change Notification Number
1100641 REV A	N/A

Product(s) Affected

Part Number(s)				
FCFM-2A-004				
Change Description				
Product is no longer available.				
Reason for Change				
Through-hole is susceptible to obstruction as the Nylon body material can shave off during assembly of the				
diverter. The high probability of flaking flash does not allow this product to consistently meet Nordson MEDICAL				
quality standards.				
Change Level				
Level 1	Level 2	Level 3	Emergency 🔀	

mplementation Procedure
Product is subject to immediate discontinuation.

Single Point of Contact	Email Address
Customer Service	sales@nordsonmedical.com