



**Nordson MEDICAL**  
805 West 71st Street  
Loveland, CO 80538, USA

+1.888.404.5837  
+1.970.267.5200  
nordsonmedical.com

## Product Change Notification

Date of Correspondence	Planned Date of Change Implementation
<i>August 6, 2020</i>	<i>January 31, 2021</i>
Change Notification Number	Sub-Supplier Change Notification Number
<i>1111390</i>	<i>N/A</i>

### *Product(s) Affected*

Part Number(s)
NEFE21-50, NEFE21-57, NEFE21-9010, NEFE31-50, NEFE31-9010, NEFC-50, NEFC-57, NEFC-8012
Change Description
Statements relating to 80369-6 Compliance will be removed from NEFE31-50, NEFE31-9010, NEFC-50, NEFC-57 and NEFC-8012.  NEFE21-50, NEFE21-57 and NEFE21-9010 will be modified to bring the dimensions into compliance with ISO 80369-6.
Reason for Change
It was found that the NEF connectors do not fully meet the dimensional requirements of ISO 80369-6, specifically in the "K" dimension which is the length of the front of the connector to the grip geometry. This dimension is critical to the function of the ISO 80369-6 connectors at all tolerance ranges, allowing the tapers to fully engage without the threads bottoming out.
Change Level
Level 1 <input checked="" type="checkbox"/> Level 2 <input type="checkbox"/> Level 3 <input type="checkbox"/> Emergency <input type="checkbox"/>

Implementation Procedure
These changes will be made effective by the end of January 2021. The current dimension will remain available for purchase until the end of January 2021, without a statement of compliance to ISO 80369-6, and will then be discontinued.

Single Point of Contact	Email Address
Customer Service	change@nordsonmedical.com