

November 12, 2021


Subject: Change to non-functional area of SBL male parts to support manufacturing processes & product quality

Parts Affected: **SBLM035-001, SBLM013-004, SBLM013-003, SBLM013-002, SBLM013-001, CA161-001, CA194-001, CA160-001 & CA195-001**

Dear Valued Customer,

You are receiving this notice because your company has purchased, or sampled, the parts referenced above from Nordson MEDICAL in the past 24 months.

We are making a change to facilitate consistent part molding and improved product quality of the above-mentioned parts. Please find the before and after change images as below.



There is no change to the part numbers nor to the internal or any sealing geometry thus the flow path will remain unaffected by this change.

You may download details of this change from our website by clicking on the link below or pasting it into your browser's window http://www.nordsonmedical.com/tech/product_changes_notification.aspx. For your reference, the product change notification (PCN) number is **1315085**.

Should you have additional questions, please contact your Nordson MEDICAL representative or email us at NMSales@nordsonmedical.com. We appreciate your business and hope that this change will have no effect on the end-product in which it is used.

Sincerely,

Ravi Narayanan
Global Product Manager
Nordson Medical