



Nordson Medical  
805 W 71<sup>st</sup> Street  
Loveland, CO 80538

September 22, 2021

RE: Nordson Medical to partner with local molding facility due to increasing demand to support Covid-19 vaccine manufacturing

Dear Valued Customers,

Nordson MEDICAL strives to provide the broadest selection of precision products with industry-leading quality and customer service. We succeed in this endeavor by maintaining the best, most efficient systems, all within our state of the art, United States operation here in Loveland, Colorado. You are receiving this notice because your organization has purchased or sampled the parts in the table below in the past 24 months.

Nordson MEDICAL is moving the molding of products in table below in a phased manner to our molding partner facility located within 40-mile radius of our Loveland, Colorado facility. It is important to note that the raw materials and finished good part numbers will not change and that there will be no change in form, fit or function of the part. Nordson Medical has taken steps to ensure that the performance characteristics and the quality of product molded at this partner facility is equivalent to that of the Loveland facility.

Please also note that all customer-facing processes and documentation will remain the same. Final quality inspection, release and shipping will occur at our Loveland, Colorado facility.

Should you have additional questions, please contact your Nordson MEDICAL representative or email us at [NMSales@nordson.com](mailto:NMSales@nordson.com). Thank you for your business, and we look forward to supporting your ongoing success.

Nordson MEDICAL  
805 W. 71st Street  
Loveland, CO 80538  
[www.NordsonMEDICAL.com](http://www.NordsonMEDICAL.com)

|        |           |         |       |              |
|--------|-----------|---------|-------|--------------|
| 1040-1 | 1860-2    | AD-1    | CCR-1 | FTLLB210-9   |
| 1040-9 | 1860-6005 | AD-6005 | CCR-4 | FTLLB210-J1A |



Nordson Medical  
805 W 71<sup>st</sup> Street  
Loveland, CO 80538

|            |              |              |              |               |
|------------|--------------|--------------|--------------|---------------|
| 1040-J1A   | 1860-CM023   | AD-J1A       | CF166-6005   | FTLLB220-1    |
| 1600-1     | 1860-CM044   | BDJ03-81     | CF224-9      | FTLLB220-2    |
| 1600-J1A   | 1860-J1A     | BDJ22-81     | CF229-5      | FTLLB220-6005 |
| 1620-2     | 18FTLL-1     | BDML210-81   | CF233-6005   | FTLLB220-J1A  |
| 16210-6005 | 18FTLL-6005  | BDML220-81   | CF236-6005   | FTLLB230-1    |
| 16220-6005 | 18FTLL-6012  | BDML230-81   | CF361-9002   | FTLLB230-2    |
| 16220-J1A  | 18FTLL-J1A   | BDML430-81   | CF362-1      | FTLLB230-6005 |
| 16230-J1A  | 18FTLL-J1A2  | BDMR210-40   | CF368-6015   | FTLLB230-9    |
| 16250-1    | 18L230-1     | BDMR210-81   | CF625-6005   | FTLLB230-J1A  |
| 16250-2    | 18L230-2     | BDMR210-9002 | CF711-20     | FTLLE-1       |
| 16250-J1A  | 18L230-6005  | BDMR220-81   | CF714-81A    | FTLLE-6005    |
| 1630-6005  | 18LFTLL-6005 | BDMR230-40   | CF771-1      | FTLLE-9       |
| 16445-1    | 18LFTLL-6012 | BDMR230-81   | CF925-2      | FTLLE-J1A     |
| 1650-1     | 18LFTLL-J1A  | BDMR445-81   | DD-1         | FTLP-1        |
| 1800-2     | 2040-6005    | BDMT220-81   | DD-6005      | FTLP-6005     |
| 1800-6005  | 3040-J1A     | BDMT430-81   | DD-J1A       | K10-6005      |
| 1800-J1A   | 3PF210-1     | BPC220-10    | ENTFTC-VP1   | K210-1        |
| 1810-1     | 3PF210-6005  | BPC250-10    | ENTM230-6005 | K210-2        |
| 1820-6005  | 3PF220-1     | BPCL220-10   | FTL10-J1A    | K210-6005     |
| 18210-1    | 3PF230-1     | BPCL230-10   | FTL210-9     | K210-J1A      |
| 18210-J1A  | 3PF230-6005  | BPI025-1     | FTL210-J1A   | K220-1        |
| 18220-1    | 4040-J1A     | BPIM-1       | FTL230-1     | K220-2        |
| 18220-2    | 4060-J1A     | BPLF230-8012 | FTL230-9010  | K220-6005     |
| 18220-J1A  | 4PLL210-1    | BPLF240-8012 | FTL230-J1A   | K220-J1A      |
| 18230-1    | 4PLL210-6005 | BPMMTLL-1    | FTL240-6005  | K230-1        |
| 18230-6005 | 4PLL220-1    | BSFTLL-1     | FTL240-J1A   | K230-2        |
| 18230-J1A  | 4PLL220-6005 | BSFTLL-6005  | FTL30-1      | K230-6005     |
| 18240-1    | 4PLL230-1    | BSFTLL-J1A   | FTL30-6005   | K230-J1A      |
| 18240-2    | 4PLL230-6005 | BSFTLL-J1A2  | FTLB210-1    | K420-20       |
| 18240-6005 | 4PX220-1     | BSMLRL-J1A   | FTLB210-6005 | K420-6005     |
| 1830-1     | 4PX220-6005  | C-4          | FTLB220-1    | K430-1        |
| 1830-6005  | 4PX230-1     | CCLR-07      | FTLB230-1    | K430-6005     |
| 18420-J1A  | 4PX230-6005  | CCLR-1       | FTLB230-20   | K430-J1A      |
| 18445-1    | 6060-J1A     | CCLR-2       | FTLB230-6005 | K445-1        |
| 1850-1     | 6PDT210-1    | CCLR-3       | FTLC-9       | K445-2        |
| 1850-2     | 6PTT210-1    | CCLR-4       | FTLC-J1A     | KL210-1       |
| 1850-6005  | 6PTT230-1    | CCLR-5       | FTLLB210-1   | KL210-6005    |
| 1860-1     | 6PTT230-6005 | CCR-07       | FTLLB210-2   | KL220-2       |

|            |         |            |              |            |
|------------|---------|------------|--------------|------------|
| KL220-6005 | M5220-1 | MTLCS-9010 | MTLS210-1    | PIP220-J1A |
| KL230-1    | M5230-1 | MTLL004-9  | MTLS210-6005 | PIP230-1   |



Nordson Medical  
 805 W 71<sup>st</sup> Street  
 Loveland, CO 80538

|               |              |               |               |                 |
|---------------|--------------|---------------|---------------|-----------------|
| KL230-6005    | M5230-6005   | MTLL007-2     | MTLS210-9     | PIP230-6005     |
| KL230-J1A     | M5240-6005   | MTLL007-5     | MTLS210-J1A   | PIP230-J1A      |
| KP-1          | M6210-1      | MTLL013-06    | MTLS220-9     | PIP240-1        |
| KP-2          | M6210-6005   | MTLL013-07    | MTLS230-6005  | PIP240-6005     |
| KP-6005       | M6220-6005   | MTLL013-1     | MTLS230-J1A   | PMK210-1        |
| KP-J1A        | M6230-1      | MTLL013-2     | MTLS240-1     | PMK210-6005     |
| KT210-1       | M6230-6005   | MTLL013-3     | MTLS240-6005  | PMK220-1        |
| KT210-J1A     | M6240-6005   | MTLL013-9002  | MTLS240-J1A   | PMK220-210-1    |
| KT230-2       | M6250-2      | MTLL025-1     | MTLSP-6005    | PMK220-210-6005 |
| L20-1         | M6250-6005   | MTLL025-2     | N004-2        | PMK220-6005     |
| L20-6005      | M6250-J1A    | MTLL025-3     | N004-6005     | PMS230-1        |
| L210-9        | M6430-2      | MTLL025-9     | N004-9        | PMS230-210-1    |
| L30-1         | M6430-6005   | MTLL035-1     | N004-J1A      | PMS230-220-1    |
| L30-2         | M6P-6005     | MTLL035-2     | N007/004-6005 | PMS230-220-6005 |
| L30-6005      | MLLR-6005    | MTLL035-4     | N007/004-9    | PMS230-6005     |
| L40-6005      | MLLR-9002    | MTLL035-6005  | N007/004-J1A  | RMLLR-5         |
| L40-J1A2      | MLRL025-1    | MTLL035-J1A   | N007-9        | RMLLR-J1A       |
| L430/410-1    | MLRL025-6005 | MTLL055-07    | N007-J1A      | S10-1           |
| L430/410-6005 | MLRL025-9    | MTLL055-1     | N007-J1A2     | S20-6005        |
| L430/420-6005 | MLRL055-6005 | MTLL055-2     | N013/004-6005 | S20-J1A         |
| L440-2        | MLRLC-1      | MTLL210-CM033 | N013/004-9    | S210-1          |
| L440-J1A      | MLRLC-6005   | MTLL210-CM072 | N013/004-J1A  | S210-6005       |
| L50-1         | MLRLC-9      | MTLL250-J1A   | N013-J1A      | S210-J1A        |
| L50-2         | MLRLP-6005   | MTLL360-J1A   | N210-9        | S220-6005       |
| L50-6005      | MLRLP-9      | MTLL410-6005  | N210-J1A      | S230-1          |
| L50-J1A       | MLSL013-9    | MTLL410-9     | N410-1        | S230-2          |
| LC78-6005     | MLSL025-1    | MTLL430-9002  | NEFC-50       | S230-6005       |
| LC78-9        | MLSL025-6005 | MTLL430-J1A   | NEFCV-50      | S230-J1A        |
| LNS-06        | MLSL025-9    | MTLL430-J1A2  | NEFCV-9010    | S240-1          |
| LNS-07        | MTL20-9      | MTLL445-J1A2  | NEFE21-50     | S240-6005       |
| LNS-1         | MTL210-1     | MTLL450-1     | NEME21-50     | S240-J1A        |
| LNS-2         | MTL210-6005  | MTLL450-9     | NEME21-9010   | S250-1          |
| LNS-3         | MTL210-9     | MTLP-1        | NEME31-50     | S250-2          |
| LNS-4         | MTL220-9     | MTLP-6005     | NEME31-9010   | S250-6005       |
| LNS-5         | MTL230-1     | MTLR210-9     | NEMP-50       | S250-J1A        |
| LNS-J1A       | MTLC-1       | MTLR220-6005  | NEMPV-50      | S30-6005        |
| M5210-1       | MTLC-6005    | MTLR230-2     | PIP220-1      | S40-1           |
| M5210-6005    | MTLCS-9      | MTLR230-6005  | PIP220-6005   | S40-J1A         |

|           |               |            |  |  |
|-----------|---------------|------------|--|--|
| S420-J1A  | TSC2F210-6005 | XT230-6005 |  |  |
| S430-6005 | U10-7         | XT430-2    |  |  |



Nordson Medical  
 805 W 71<sup>st</sup> Street  
 Loveland, CO 80538

|               |            |           |  |  |
|---------------|------------|-----------|--|--|
| S445-1        | U30-2      | Y090-6005 |  |  |
| S50-1         | X10-1      | Y090-J1A  |  |  |
| S50-6005      | X10-J1A    | Y100-6005 |  |  |
| SMLRL-6005    | X210-2     | Y100-J1A  |  |  |
| SP-1          | X210-6005  | Y110-6005 |  |  |
| SP-2          | X210-J1A   |           |  |  |
| SP-6005       | X220-1     |           |  |  |
| T20-1         | X220-2     |           |  |  |
| T20-6005      | X220-6005  |           |  |  |
| T210/230-1    | X220-J1A   |           |  |  |
| T210-J1A      | X230-1     |           |  |  |
| T220/230-1    | X230-2     |           |  |  |
| T220/230-6005 | X230-5     |           |  |  |
| T220/230-9    | X230-6005  |           |  |  |
| T220/230-J1A  | X230-J1A   |           |  |  |
| T230/210-J1A  | X240-1     |           |  |  |
| T230/220-1    | X240-5     |           |  |  |
| T230/220-2    | X240-6005  |           |  |  |
| T230/220-J1A  | X410-2     |           |  |  |
| T230-5        | X420-1     |           |  |  |
| T230-J1A      | X420-J1A   |           |  |  |
| T230R210-1    | X430-1     |           |  |  |
| T230R210-6005 | XL210-2    |           |  |  |
| T230R220-1    | XL210-J1A  |           |  |  |
| T230R220-J1A  | XL220-2    |           |  |  |
| T30-2         | XL220-6005 |           |  |  |
| T30-J1A       | XL230-1    |           |  |  |
| T40-6005      | XL230-2    |           |  |  |
| T40-J1A       | XL230-J1A  |           |  |  |
| T40-J1A2      | XL420-J1A  |           |  |  |
| T410/430-6005 | XL430-J1A  |           |  |  |
| T410-1        | XP-1       |           |  |  |
| T430/420-1    | XP-2       |           |  |  |
| T430-1        | XP-J1A     |           |  |  |
| T430R420-1    | XT210-2    |           |  |  |
| T50-2         | XT210-J1A  |           |  |  |
| T50-6005      | XT220-2    |           |  |  |
| TSC2F007-6005 | XT230-1    |           |  |  |