





Product Change Notification

Product Change #: 1072988

Posting Date: 1/11/2019

Description of Change: The previously communicated maximum back pressure of 8bar has been redefied at 5 bar, for the following part numbers: SCV67220, SCV67200/230, SCV67220/ML, SCV67230, SCV67230/220, SCV67230/ML, SCV67FL/220, SCV67FL/230, SCV06265, SCV06018. There will be no physical changes made to these parts.

Reason: Review of inspection results over the production lifespan has shown that the current acceptable back pressure is close to the maximum load, and 8bar cannot be guaranteed. The maximum back pressure of these part numbers has been redefined at 5bar. However, compliance with ISO 8536-12 (chapter 6.5, backflow of 2bar for 15 minutes) will be maintained

Parts Affected: SCV67220, SCV67200/230, SCV67220/ML, SCV67230, SCV67230/220, SCV67230/ML, SCV67FL/220, SCV67FL/230, SCV06265, SCV06018

Effective Date: 1/11/2019

Implementation Procedure: This change aligns the communicated specifications with actual performance.