


Product Change Notification

Product Change #: 283 Affecting Guarded Sub-assembly VPS5069200N and Spike VPM8240601N

Posting Date: **November 17, 2014**

Description of Change:

1. Spike geometry of the Guarded Sub-assembly VP P/N VPS5069200N is changing to be in compliance to ISO8536-4:2010. The part number of the sub-assembly will remain the same.



2. Spike VPM8240601N will be obsolete.

Reason: To be in compliance with ISO8536-4:2010

Parts Affected: VPS5069200N and Spike VPM8240601N

Effective Date: Jan 15, 2015

Implementation Procedure: Running change.