

## **Product Change Notification**

Droduct Change #. 224
Product Change #: 334
Posting Date: June 29, 2016
1. Description of Change: Change in drawing to match product dimensions. Change the Thru Hole from .117" +/005" to .112" +/005"
Reason: Have been running under deviation.
Parts Affected: BPC240
Effective Date: Immediately
Implementation Procedure: None. Document change only.