



Nordson MEDICAL  
 805 West 71st Street  
 Loveland, CO 80538, USA

+1.888.404.5837  
 +1.970.267.5200  
 nordsonmedical.com

## Product Change Notification

Product Change #: 345

Posting Date: 01/20/2017

Description of Change:  
  
 TBA parts are changing to DEHP free.

Reason:  
  
 Supplier has made the change. Customers are requesting DEHP free parts.

Description of change:  New part numbers created for the DEHP FREE parts.	<table border="1" style="width: 100%; border-collapse: collapse; background-color: #0070C0; color: white;"> <thead> <tr> <th style="text-align: left;">Current P/N</th> <th style="text-align: left;">New P/N</th> </tr> </thead> <tbody> <tr><td><b>TBA2100-001</b></td><td><b>TBA2100-002</b></td></tr> <tr><td><b>TBA2062-001</b></td><td><b>TBA2062-002</b></td></tr> <tr><td><b>TBA2052-001</b></td><td><b>TBA2052-002</b></td></tr> <tr><td><b>TBA2040-001</b></td><td><b>TBA2040-002</b></td></tr> <tr><td><b>TBA2081-001</b></td><td><b>TBA2081-002</b></td></tr> <tr><td><b>TBA2025-001</b></td><td><b>TBA2025-003</b></td></tr> <tr><td><b>TBA4030P-001</b></td><td><b>TBA4030P-003</b></td></tr> <tr><td><b>TBA2025-002</b></td><td><b>TBA2025-004</b></td></tr> <tr><td><b>TBA4030P-002</b></td><td><b>TBA4030P-004</b></td></tr> <tr><td> </td><td> </td></tr> </tbody> </table>	Current P/N	New P/N	<b>TBA2100-001</b>	<b>TBA2100-002</b>	<b>TBA2062-001</b>	<b>TBA2062-002</b>	<b>TBA2052-001</b>	<b>TBA2052-002</b>	<b>TBA2040-001</b>	<b>TBA2040-002</b>	<b>TBA2081-001</b>	<b>TBA2081-002</b>	<b>TBA2025-001</b>	<b>TBA2025-003</b>	<b>TBA4030P-001</b>	<b>TBA4030P-003</b>	<b>TBA2025-002</b>	<b>TBA2025-004</b>	<b>TBA4030P-002</b>	<b>TBA4030P-004</b>		
Current P/N	New P/N																						
<b>TBA2100-001</b>	<b>TBA2100-002</b>																						
<b>TBA2062-001</b>	<b>TBA2062-002</b>																						
<b>TBA2052-001</b>	<b>TBA2052-002</b>																						
<b>TBA2040-001</b>	<b>TBA2040-002</b>																						
<b>TBA2081-001</b>	<b>TBA2081-002</b>																						
<b>TBA2025-001</b>	<b>TBA2025-003</b>																						
<b>TBA4030P-001</b>	<b>TBA4030P-003</b>																						
<b>TBA2025-002</b>	<b>TBA2025-004</b>																						
<b>TBA4030P-002</b>	<b>TBA4030P-004</b>																						

Effective Date:

New P/N	Change Timing
<b>TBA2100-002</b>	<b>FEB 2017</b>
<b>TBA2062-002</b>	<b>FEB 2017</b>
<b>TBA2052-002</b>	<b>FEB 2017</b>
<b>TBA2040-002</b>	<b>FEB 2017</b>
<b>TBA2081-002</b>	<b>FEB 2017</b>
<b>TBA2025-003</b>	<b>FEB 2017</b>
<b>TBA4030P-003</b>	<b>NOV 2016</b>
<b>TBA2025-004</b>	<b>FEB 2017</b>
<b>TBA4030P-004</b>	<b>NOV 2016</b>



**Nordson MEDICAL**  
805 West 71st Street  
Loveland, CO 80538, USA

+1.888.404.5837  
+1.970.267.5200  
nordsonmedical.com

Implementation Procedure:  
New part numbers will be assigned to lots with changes to ensure proper traceability of the said change